

Inventory & Check In

1 Example Road, Template, AB12 3YZ



Date of Report	30 th May 2017
Reference No	082
Tenants Name	
Prepared By	Diamond Inventories
	1 Stroma Gardens
	Hailsham
	East Sussex
	BN27 3AZ
	07484511729
	info@diamondinventories.co.uk
Working with and on	
behalf of	

Page 1

Inventory Index

- 1. Cover
- 2. Index
- 3. Disclaimer
- 4. Property Details
- 5. Services
- 6. Porch, Entrance Door & Hallway
- 7. Lounge
- 8. Kitchen/Dining Room
- 9.Orangery
- 10.Downstairs W.C
- 11.Stairs and Landings
- 12.Bedroom 1 & En-Suite
- 13.Bedroom 2
- 14.Bedroom 3
- 15.Bathroom
- 16.Front & Rear Garden
- 17.Garage
- 18.Keys
- 19.Declaration

^{age}2

Disclaimer

It is advised that all parties read these notes very carefully.

This report is deemed as a fair and accurate report which describes the property's condition, cleanliness and contents for rental purposes only. This report is no guarantee of, or report on, the adequacy of, or safety of any such equipment of contents, merely a record that such items exist in the property as at the date of the report and the superficial condition of the same. The report does not constitute a valuation or statement of authenticity and has been prepared for identification purposes only.

As such the report only extends to parts of the property that are readily accessible i.e. attics/lofts, garages, sheds, cellars or locked rooms and are the sole responsibility on the landlord.

Unless otherwise stated, it is accepted that any listed item is in good condition and free from any obvious defects. A significant defect is normally seen as damage, staining or soiling, excess wear or usage which may, upon termination of the tenancy constitute a discrepancy assessment.

The preparation of this report does not include the testing of any gas or electrical appliances, boilers, radiators, machinery or water supply and other similar items. Lighting is solely tested to indicate if the light bulbs are working at the time of the report but this is not an indication of correct functioning or compliance with current safety regulations.

Burglar alarms and smoke detectors will be listed but are not tested. Smoke detectors are the responsibility of the tenant to inspect both at the start of and throughout the tenancy.

The person preparing the report is not a qualified surveyor and they are not an expert on wood, materials, fabrics or antiques etc. Heavy appliances or furniture will not be moved and therefore the condition of areas obstructed from view will not have been identified.

Meter readings will be taken wherever possible. However, if they are inaccessible, the Landlord and tenant should make their own arrangements for the meters to be read.

Where the report notes "Fire label seen" this should not be interpreted as to mean the item complies with the Furniture and Furnishings (Fire) (Safety) Regulations 1988 as amended 1993. It is a record that at the time of making the report it had a label described or similar to that detailed in the "Guide to the Furniture and Furnishings" (Fire) (Safety) Regulations as published by the department of Trade and Industry, January 1997. It is not a statement that the item can be considered to comply with Regulations.

The Tenant should check all electrical appliances in the property and read through this inventory within 7 days from the "check in". Should there be any discrepancies these must be brought to the attention on the agent and in turn to us at Diamond Inventories.co.uk. Amendments to the initial condition can only be submitted during this period and will not be accepted at any time after.

Property Details

Is the property occupied?	NO
Is the property furnished?	NO
Type of property	House
	Detached

General Notes

The condition and cleanliness of the property was very good



Front View

Page4

Services

Туре	Meter Location/Accessible	Supplier
Gas	Yes, in front garden	
Electric	Yes, in porch	

Meter Readings

Туре	Reading	Serial Numbers/Notes
Gas	16946 79 1	G4 K5021569 03
Electric	59607	D9976451

Gas

Electric



Fuseboard



 $\mathsf{Page} \mathbf{5}$

Porch, Entrance Door & Hallway





Item	Description	Condition	Check Out
Porch	-uPVC double glazed porch on front	Outside tap (Pic 1)	
	of house with sliding door	Light (Pic 2)	
	-Paving slab flooring	Pictures (Pic 3-4)	
	-Outside tap	Wooden cross plaque	
	-White round ceiling light	(Pic 5)	
	-Mosaic style pictures	Animal ornaments (Pic 6)	
	-Wooden horse design cross plaque	Tree (Pic 7)	
	-Animal ornament's	Mat <mark>(Pic 8)</mark>	
	-Small fake tree with yellow flowers		
	-Pheasant design coconut mat		
Entrance Door	-Large green painted panelled front	Front door <mark>(Pic 9)</mark>	
	door with large brass knob and small		
	glass pane		
Ceiling	-Flat white painted ceiling and		
	coving		
Walls	-Pale yellow painted walls	Picture hooks (Pic 10-14)	
Flooring/Carpets	-Beige carpet with recessed coconut	Carpet in good condition	
	mat	(Pic 15)	
Internal Doors	-3x White panelled internal doors		
	with gold handles		
Switches &	-2x Double light switches		
Sockets	-1x Dimmer switch		
	-1x Single socket		
	-1x Phone point		
Lights	-2x Single pendant ceiling lights 1x	Lights (Pic 16-17)	
	Glass shade and 1x brass patterned		
	glass dome shade		
Woodwork	-White wooden skirting boards and		
	door frames		
Additional Items	-Honeywell Thermostat	Thermostat (Pic 18)	
	-Security alarm box	Alarm box (Pic 19)	
	-Smoke detector – NOT TESTED	Built in cupboard (Pic 20)	
	-Built in cupboard with coat hook		

 $\mathsf{Page} 6$

Pic 1 – Outside tap



Pic 4 -Pictures



Pic 7 - Tree



Pic 10 -Picture hooks



Pic 13 - Picture hooks



Pic 2- Porch light



Pic 5- Wooden cross plaque



Pic 8- Mat



Pic 11- Picture hooks



Pic 14- Picture hooks



Pic 3 - Pictures



Pic 6 – Animal ornaments



Pic 9 – Front door



Pic 12 – Picture hooks




Pic 15 - Carpet



Page /

Pic 16 -Lights



Pic 19 – Alarm box







Pic 20- Built in cupboard



Pic 18 - Thermostat



Page 8

<u>Lounge</u>



Item	Description	Condition	Check Out
Ceiling	-Flat white painted ceiling and coving		
Walls	-Yellow painted walls	4x Matching curtain tie hooks (Pic 1)	
Flooring/Carpets	-Beige carpet	Carpet has some indents from previous furniture (Pic 2)	
Window, Frame &	-uPVC double glazed window		
door	with diamond lead design		
	-uPVC double glazed double		
	doors with diamond lead design		
	leading to rear garden		
Curtains and tracks	-Matching white wooden curtain poles and rings	Curtain poles (Pic 3-4)	
Switches & Sockets	-1x Double dimmer switch		
	-4x Double sockets		
	-1x blanking plate		
Lights	-10x Silver spotlights	Spotlights (Pic 5)	
Woodwork	-White wooden skirting boards		
	and door frame		
Additional Items	-Patterned framed large mirror	Mirror (Pic 6)	
	-Cream painted wall hung book	Bookcase (Pic 7)	
	case		

Pic 1 – Curtain tie hooks







Pic 3 – Curtain poles



 $\mathsf{Page}9$

Pic 4 – Curtain poles

Pic 5- Spotlights

Pic 6 - Mirror



Pic 7 - Bookcase







 $_{\mathsf{Page}} 1 \mathsf{C}$

Kitchen/Dining Room





Item	Description	Condition	Check Out
Ceiling	-Flat white painted ceiling and		
	coving		
Walls	-Cream painted walls and neutral	Picture hooks (Pic 1-7)	
	coloured tiles between worktop		
	and wall units in kitchen area		
	-Red painted walls with a wood		
	and cream painted cladding in		
	dining area		
Flooring/Carpets	-Multi coloured tile effect vinyl	Vinyl floor is brand new	
	flooring in kitchen area	(Pic 8)	
	-Beige carpet in dining area	Carpet (Pic 9)	
Window, Frame	-uPVC double glazed large		
and Back door	window with diamond lead design		
	-uPVC double glazed small		
	window with diamond lead design		
	-uPVC double glazed back door		
	with glass pane and cat flap		
Blind	-Pink stripy blind on small window	Blind (Pic 10)	
Kitchen Units	-Cream panelled wall and floor	Kitchen units (Pic 11-12)	
	units with decorative handles	Boat plaque <mark>(Pic 13)</mark>	
	-Boat design plaque above cooker	Worktop <mark>(Pic 14)</mark>	
	-Red worktop		
Appliances	-2x Stainless steel sinks with silver	Sinks (Pic 15-16)	
	mixer taps	Cooker (Pic 17)	
	-Red and black Aga style cooker		
Switches & Sockets	-1x Single light switch		
	-5x Double sockets		
	-Cooker switch and socket		
	-2x Switched fused spur		
	-1x Single socket		
Lights	-12x Silver spotlights	Spotlights (Pic 18)	
	-Single pendant ceiling light with	Pendant light (Pic 19)	
	dragonfly design glass dome		
	shade		
Additional Items	-Worchester boiler	Boiler (Pic 20)	
	-Large wooden framed mirror	Mirror <mark>(Pic 21)</mark>	
	-Red square clock	Clock (Pic 22)	
	-Hot water and heating	Programmer (Pic 23)	
	programmer	Key hook <mark>(Pic 24)</mark>	
	-Cow shed style key hook		

Tenants Initials

Page 1.

Pic 1 – Picture hooks



Pic 4 -Picture hooks



Pic 7 -Picture hooks



Pic 10 - Blind



Pic 13 -Boat plaque



Pic 16 - Sink



Pic 2- Picture hooks



Pic 5- Picture hooks



Pic 8- Vinyl flooring



Pic 11- Kitchen units



Pic 14- Worktop



Pic 17- Cooker



Pic 3 – Picture hooks



Pic 6 – Picture hooks



Pic 9 - Carpet



Pic 12 – Kitchen units



Pic 15 - Sink



Pic 18 - Spotlights





Pic 22 - Clock



Pic 20- Boiler



Pic 23- Programmer



Pic 21 - Mirror



Pic 24 – Key hook



Tenants Initials

Downstairs W.C



Item	Description	Condition	Check Out
Ceiling	-Flat white painted ceiling and		
	coving		
Walls	-Cream painted top half of walls	Picture hooks (Pic 1-3)	
	and wooden cladding on bottom		
	half		
Window and	-White painted wooden framed		
frame	window with opaque glass and		
	diamond lead design		
Flooring	-Beige carpet	Carpet (Pic 4)	
Lighting	-Ceiling light with glass shade	Light (Pic 5)	
W.C	-White W.C with boat design seat	W.C (Pic 6)	
	and silver button flush		
Sink	-Small white sink with silver mixer	Sink (Pic 7)	
	tap in a wooden cupboard		
Wall Items	-Silver toilet roll holder	Toilet roll holder (Pic 8)	
	-Silver towel ring	Towel ring (Pic 9)	
Switches	-Pull cord light switch with	Weight (Pic 10)	
	patterned weight		
Additional	-Blue mat around W.C	Mat (Pic 11)	
	-Round window picture	Picture (Pic 12)	
	-Wooden shelves	Shelves (Pic 13)	

Pic 1 – Picture hooks



Pic 2- Picture hooks



Pic 3 – Picture hooks



 $_{\text{Page}}14$



Pic 7 - Sink



Pic 10 – Pull cord weight



Pic 13 -Wooden shelves



2 6

Pic 5- Light

Pic 8- Toilet roll holder



Pic 11- Mat



Pic 6 – W.C



Pic 9 – Towel ring



Pic 12 – Window picture



Page 1

Orangery



Item	Description	Condition	Check Out
Windows	-uPVC double glazed windows and		
	door with cat flap		
Roof	-uPVC double glazed pitched roof	Roof (Pic 1)	
Ceiling	-White painted flat ceiling and	Crack in corner of coving	
	coving	(Pic 2)	
Walls	-Light blue painted walls	Cracks in walls (Pic 3-4)	
		Picture hooks (Pic 5-7)	
Flooring	-Multi coloured striped carpet and	Carpet is brand new (Pic 8)	
	recessed coconut mat	Coconut mat (Pic 9)	
Lighting	-8x Silver spotlights	Spotlights (Pic 10)	
Switches	-1x Single dimmer switch		
	-2x Double sockets		
Woodwork	-White wooden skirting boards		
Additional	-White wood burner on a marble	Wood burner (Pic 11)	
	style hearth	Mat (Pic 12)	
	-Small coconut mat	Plant (Pic 13)	
	-Large plant in grey pot		

Pic 1 - Roof



Pic 4 – Crack on wall







Pic 5- Picture hooks



Pic 3 – Crack on walls



Pic 6 – Picture hooks



 ${}^{\rm Page}16$

Pic 7 – Picture hooks



Pic 10 - Spotlights



Pic 13 - Large plant



Pic 8- Carpet



Pic 11- Wood burner



Pic 9 – Coconut mat



Pic 12 – Small mat



Page1,

Stairs & Landing





ltem	Description	Condition	Check Out
Ceiling	-White painted textured ceiling		
	and coving		
Walls	-Yellow painted walls on top half	Picture hooks (Pic 1-4)	
	of walls and wooden cladding on		
	bottom half		
Flooring/Carpets	-Beige carpet	Carpet is in good	
		condition	
		(Pic 5)	
Internal Doors	- 6x White panelled internal doors		
	with gold handles		
Window & Frame	-Large uPVC double glazed		
	window with diamond lead design		
Curtains & Track	-Black curtain pole with cream	Curtains and pole (Pic 6)	
	stripe curtains		
Switches &	-1x Single light switch		
Sockets	-1x Single socket		
Lights	-Single pendant chandelier style	Light (Pic 7)	
	ceiling light		
Woodwork	-White wooden skirting boards	Staircase (Pic 8)	
	and door frames		
	-Wooden stair case and handrail		
Additional Items	-Loft hatch	Loft hatch <mark>(Pic 9)</mark>	

Pic 1 – Picture hooks





Pic 2- Picture hooks


Pic 3 – Picture hooks



 ${}^{\text{Page}}18$

Pic 4 – Picture hooks

Pic 5- Carpet





Pic 7 - Light





Pic 8- Staircase





Pic 9 – Loft hatch



 ${}^{\text{Page}}19$

Bedroom 1 & En-Suite





Item	Description	Condition	CheckOut
Ceiling	-Flat white painted ceiling and		
	coving		
Walls	-Pale pink painted walls	Picture hooks and holes	
		(Pic 1-6)	
		Marks on walls (Pic 7-10)	
Flooring/Carpets	-Light pink carpet	Carpet is in good	
		condition	
		(Pic 11)	
Window and	-2x uPVC double glazed windows		
Frame	with diamond lead design		
Curtains and	-2x matching curtain poles and	Curtain poles (Pic 12)	
tracks	rings		
Switches &	-2x Single light switches		
Sockets	-2x Double sockets		
Lights	-2x Single pendant ceiling lights 1x	Lights (Pic 13-14)	
	with glass shade and 1x with glass		
	dome shade		
Woodwork	-White wooden skirting boards and		
	door frames		
Additional Items	-3x Built in wardrobes with hanging	Wardrobes (Pic 15)	
	rails, shelves and shoe rack		
	-Mirror on inside of door		
En-Suite	-Flat white painted ceiling and	Crack in tile grout (Pic	
	coving	16)	
	-Cream painted walls and blue	Bath (Pic 17)	
	painted wooden cladding	Shower <mark>(Pic 18)</mark>	
	-White wall tiles with scattered	Shower curtain and rail	
	blue glass tiles	(Pic 19)	
	-White bath with blue wooden side	W.C (Pic 20)	
	panel and silver hot and cold taps	Sink (Pic 21)	
	-Silver shower unit with silver	Ceiling light (Pic 22)	
	shower curtain rail and white	Wall light (Pic 23)	
	curtain	Towel rail (Pic 24)	
	-White W.C with wooden seat and	Cupboard (Pic 25)	
	silver button flush	Hook (Pic 26)	
	-Blue ceramic sink sunken into blue		
	painted vanity style cupboard		
	-Silver dome ceiling light and		
	matching rectangle wall light		

 ${}^{\rm Page}20$

En-Suite	-Silver heated towel rail	
Continued	-Wooden wall hung cupboard with	
	mirror door	
	-Beige carpet	
	-Silver hook on back for door	
	-uPVC double glazed window with	
	diamond lead design opaque glass	

Pic 1 – Picture hooks



Pic 4 – Picture hooks



Pic 7 – Marks on walls



Pic 10 -Marks on walls



Pic 13 - Lights



Pic 2- Picture hooks



Pic 5- Picture hooks



Pic 8- Marks on walls




Pic 11- Carpet



Pic 14- Lights



Pic 3 – Picture hooks



Pic 6 – Picture hooks



Pic 9 – Marks on walls




Pic 12 – Curtain pole



Pic 15 - Wardrobes



Pic 16 – Crack in tile grout



Pic 19- Shower curtain and rail




Pic 22 – Ceiling light



Pic 25 - Cupboard



Pic 17- Bath



Pic 20- W.C



Pic 23- Wall light



Pic 26- Hook



Pic 18 - Shower



Pic 21 -Sink



Pic 24 – Towel rail



Page 22

Bedroom 2



Item	Description	Condition	Check Out
Ceiling	-Flat white painted ceiling and	Crack in corner of coving	
	coving	(Pic 1)	
Walls	-Pale yellow painted walls		
Flooring/Carpets	-Beige carpet	Small stain on carpet (Pic 2)	
Window and	-uPVC double glazed window with		
Frame	diamond lead design		
Curtains and tracks	-Wooden curtain pole with	Curtains and pole (Pic 3)	
	patterned curtains		
Switches & Sockets	-1x Single light switch		
	-1x Double socket		
Lights	-Single pendant ceiling light with	Light (Pic 4)	
	no shade		
Woodwork	-White wooden skirting boards		
	and door frame		
Additional Items	-Large built in wardrobes with	Wardrobes (Pic 5)	
	mirror sliding doors, hanging rail		
	and shelves		

Pic 1 – Crack in coving



Pic 4 - Light







Pic 5- Wardrobes









Bedroom 3



Item	Description	Condition	Check Out
Ceiling	-Flat white painted ceiling and		
	coving		
Walls	-Yellow painted walls	Small dent behind door	
		(Pic 1)	
Flooring/Carpets	-Beige carpet	Carpet (Pic 2)	
Window and	-uPVC double glazed window with		
Frame	diamond lead design		
Curtains and tracks	-Wooden curtain pole with green	Curtains and pole (Pic 3)	
	spotty curtains		
Switches & Sockets	-1x Single light switch		
	-2x Double sockets		
	-1x Phone point		
Lights	-7x Silver spotlights	Spotlights (Pic 4)	
Woodwork	-White wooden skirting boards		
	and door frame		

Pic 1 – Small dent on wall



Pic 4 - Spotlights







Pic 3 – Curtain and pole



<u>Bathroom</u>



Item	Description	Condition	Check Out
Ceiling	-Flat white painted ceiling		
Walls	-Cream painted top half of walls and blue painted wooden cladding on bottom half -White tiles with seashell border tile		
Window and frame	-uPVC double glazed window with diamond lead design and opaque glass		
Curtain and Track	-Wooden curtain pole -Cream curtains with seashell pattern	Curtain and pole (Pic 1)	
Flooring	-Pink carpet	Carpet (Pic 2)	
Lighting	-3x Silver matching spotlights -1x Larger spotlight in shower enclosure	Spotlights (Pic 3-4)	
W.C	-White W.C with wooden seat and silver button flush	W.C (Pic 5)	
Sink	-White corner sink with large corner cupboard painted blue with wooden door and silver mixer tap	Sink (Pic 6)	
Shower enclosure	-Large corner shower enclosure with sliding glass doors and silver shower unit	Shower enclosure (Pic 7) Shower (Pic 8)	
Wall Items	-Silver extendable mirror -White framed mirror -Large picture of boats -Silver heated towel rail	Silver mirror (Pic 9) White mirror (Pic 10) Picture (Pic 11) Towel rail (Pic 12)	
Switches	-Pull cord light switch with starfish design weight	Starfish weight (Pic 13)	
Additional	-White striped toilet brush	Toilet brush (Pic 14)	

Pic 1 – Curtains and track



Pic 4 - Spotlights



Pic 7 – Shower enclosure



Pic 10 - White mirror



Pic 13 -Starfish weight



Pic 2- Carpet



Pic 5- W.C



Pic 8- Shower



Pic 11- Picture



Pic 14- Toilet brush



Pic 3 - Spotlights



Pic 6 - Sink



Pic 9 – Silver mirror



Pic 12 – Towel rail





Front & Rear Garden





Item	Description	Condition	Check Out
Front garden	-Mainly laid to lawn with large	Lawn (Pic 1-2)	
	bushes and small trees	Flowerbeds and pots (Pic	
	-Flowerbeds border lawn with	3-6)	
	plants and flowers	Patio area (Pic 7)	
	-Flower pots	Outside light (Pic 8)	
	-Patio area with side gate leading	Hanging basket (Pic 9)	
	to rear garden		
	-Glass ball outside light		
	-Hanging basket with flowers		
Driveway and	-Large driveway leading to double	Driveway (Pic 10)	
garage	garage with brown up and over	Garage (Pic 11)	
	doors	White cupboards (Pic 12)	
	-Garage is mainly empty with a		
	couple of white cupboards, white		
	worktop and stainless steel sink		
	with mixer taps		
Rear garden	-Rear garden is on 2 levels mainly	Rear lawn <mark>(Pic 13)</mark>	
	laid to lawn with a large tree	Flower beds, trees and	
	-Large flower beds border the	pots	
	garden with large bushes and	(Pic 14-18)	
	plants	Patio area <mark>(Pic 19)</mark>	
	-Large raised patio area with steps	Pond (Pic 20)	
	and path leading to lower level	Shed (Pic 21)	
	-Large pond	Bird house (Pic 22)	
	-Potting shed	Reindeer (Pic 23)	
	-Large white wooden bird house	Ornaments (Pic 24-25)	
	-Willow Reindeer	Bird bath (Pic 26)	
	-Garden ornaments	Outside tap and hose (Pic	
	-Bird bath	27)	
	-Outside tap with long green hose	Concrete space (Pic 28)	
	pipe	Table and chairs (Pic 29)	
	-Concrete side space with green		
	water butt		
	-White metal square table and		
	chairs		

Page 27

Pic 1 – Front lawn



Pic 4 – Flower beds



Pic 7 – Patio area



Pic 10 - Driveway



Pic 13 – Rear lawn



Pic 2- Front lawn



Pic 5- Flower beds



Pic 8- Outside light



Pic 11- Garage



Pic 14- Flower beds, tree & pots



Pic 3 – Flower beds



Pic 6 – Flower beds



Pic 9 – Hanging basket



Pic 12 – Cupboards



Pic 15 -Flower beds, tree & pots





Pic 16 – Flower beds, tree & pots



Pic 19 – Patio area



Pic 22 - Bird house



Pic 25 – Garden ornaments



Pic 28 – Concrete space



Pic 17- Flower beds, tree & pots



Pic 20- Pond



Pic 23- Reindeer



Pic 26- Bird bath



Pic 29- Table and chairs



Pic 18 – Flower beds, tree & pots



Pic 21 - Shed



Pic 24 – Garden ornaments




Pic 27 – Outside tap





<u>Keys</u>

Number of keys	4x Keys
Key Function	4x Front door keys





Declaration

This report is deemed as a fair and accurate report which describes the property's condition, cleanliness and contents for rental purposes only. This report is no guarantee of, or report on, the adequacy of, or safety of any such equipment or contents, merely a record that such items exist in the property as at the date of the report and the superficial condition of the same. The report does not constitute a valuation or statement of authenticity and has been prepared for identification purposes only. All tenants are reminded that it is their responsibility to check the accuracy of this report and to sign confirming that they have read and understood the terms and conditions relating to it.

The tenant/s are to read and sign the copy of this form. Should there be any discrepancies these must be brought to the attention of the agent or Diamond Inventories clerk at 'Check In'. Amendments to the initial condition can only be submitted during this period and will not be accepted any time after.

Inventory Clerk/ Agent	Tenant
Signature:	Signature:
Print Name:	Print Name:
Date	Date: